UNCLASSIFIED

AD NUMBER AD510833 **CLASSIFICATION CHANGES** TO: unclassified confidential FROM: LIMITATION CHANGES TO: Approved for public release, distribution unlimited FROM: Controlling DoD Organization. Assistant Chief of Staff for Force Development [Army], Washington, DC 20310. **AUTHORITY** GDS, DoD 5200.1-R; AGO D/A ltr, 29 Apr 1980

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER LOD DIRECTIVE 5200.20 AND

NO RESTRICTIONS ARE IMPOSED UPON

1 '3 USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

SECURITY MARKING

The classified or limited status of this report applies to each page, unless otherwise marked.

Separate page printouts MUST be marked accordingly.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U.S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.



DEPARTMENT OF THE ARMY

CONFIDENTIAL

OFFICE OF THE ADJUTANT BUREAU

WASHINGTON, D.C. 20310

IN REPLY REFER TO

r **(?**?)

AGDA (M)

(17 Aug 70)

FOR OT UT 702059

28 August 1970

3

5

∞

SUBJECT: Operational Report - Lessons Learned, Headquarters, 11th
Aviation Battalion (Combat), Period Ending 30 April 1970 (U)

SEE DISTRIBUTION

SEE DISTRIBUTION

- 1. Subject report is forwarded for review and evaluation in accordance with paragraph 4b, AR 525-15. Information of actions initiated as a result of subject report should be forwarded to ACSFOR OT UT within 90 days of receipt of covering letter.
- 2. Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

l Incl

as

finneth G. Neicklam

KENNETH G. WICKHAM Major General, USA The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

US Army Materiel Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Air Defense School

US Army Armor School

US Army Aviation School

US Army Engineer School

US Army Field Artillery School

US Army Infantry School

Regraded unclassified when separated from classified inclosure.

CONFIDENTIAL

DISTRIBUTION (Cont'd)
US Army Ordnance School
US Army Transportation School

Copies furnished:
Office, Chief of Staff, US Army
Deputy Chiefs of Staff
Chief of Research and Development
Assistant Chiefs of Staff
Chief of Engineers
Commanding General, US Army Flight Training Center
Commandant of the Marine Corps
Defense Documentation Center
USAF Project RAND
Commanding Officers
US Army Limited War Laboratory
USAF Army Logistics Doctrine Systems & Readiness Age

US Army Logistics, Doctrine Systems & Readiness Agency
US Army Mobility Equipment Research & Development Center

DEPARTMENT OF THE ARMY HEADQUARTERS, 11TH AVIATION BATTALION (COHBAT) APO SAN FRANCISCO 96299

"EXEMPL" PROPONERE"

WABICH-YC

13 May 1970

SUBJECT: Operational Report-Lessons Learned of the 11th Aviation Battalion (Combat), for Quarterly Period Shding 30 April 1970, RCS CSFOR-65 (R2) (U)

SEE DISTRIBUTION

- 1. (C) Operations: Significant Activities.
 - a. (U) Mission. There were no mission changes.
 - b. (U) Organization.
- (1) Under the provisions of General Order 011, Headquarters, 12th Aviation Group (Combat), dated 5 April 1970, the INFANT (INSURE 100) Now Equipment Training Team was attached to the 11th Aviation Battalion (Combat), APO 96289. (See Inclosure 1.)
- (2) An organisational chart depicting the composition of the 11th Aviation Battalian (Combat) may be found at Inclosure 2.
 - c. (U) Command and Staff.
- (1) Significant changes in the 11th Aviation Battalion (Combat) command and staff structure during this reporting period are:

Command

(a) On 2 April 1970, LTC Harry McK. Roper Jr., CE, assumed command of the 11th Aviation Battalion (Combat), from LTC Rotert W. Flint, CE, and the command of the 11th Aviation Battalian (Combat), from LTC

FOR OT UT
702059
Inclosure

1

DOWNSRAFED AT 3 YEAR BITTERVALS, DECLASSIFED AFTER 12 YEARS. DOD BER 1700.19

CONFIDENTIAL

AVELCA-AC
SUBJECT: ORLL for Period Shding 30 April 1970, RCS CSFOR-65 (R2) (U)

Staff

- (b) On 13 April 1970, CPT Harvey R. Allen, III, replaced CPT James E. Tomlin, IN, as Cattalion S1.
- (c) On 9 February 1970, CPT Thomas R. Dowling, III, replaced CPT Edward W. Parker, FA, as Battalion S2.

Unit Commanders

- (d) On 21 February 1970, MAJ Glenn A. Brown, SC, assumed command of the 128th Aviation Company (Assault Helicopter) from MAJ Thomas A. Mnudtzen, IN.
 - (2) The current command and staff structure is reflected at Inclosure 3.
 - d. (U) Unit strongths (as of 30 April 1970).
 - (1) Hilitary.

<u>UNIT</u>	OF F AUTI			PPD	AUTH	-		PPD
ннс	21	23	6	12	107	99	134	134
432d Hod Det	1	1	0	0	7	7	8	. 8
128th Avn Co (Aslt Hel)	19	16	51	52	218	200	268	268
173d Avr. Co (Aslt Hel)	19	16	51	50	218	2 09	288	275
759th Mod Dot	1	1	0	0	7	7	8	8
205th Avn Co (Aslt Spt Hol)	15	9	26	19	227	176	268	204
213th Avn Co (Aslt Spt Hol)	<u>15</u>	11	_26	19	_227	186	_268	216
TOTAL 11th Avn Dn (Cbt)	91	77	160	152	1011	664	1262	1113

AVUNCA-AC 13 May 1970 SUBJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

(2) Civilian.

TINU		AC PFD	IV HTUA		3a/		TECH AUTH	
HIC	5	0	10	10	0	0	2	2
432d Led Det	0	0	1	1	0	0	0	0
128th Avn Co (Aslt Hel)	0	0	10	9	0	0	0	0
173d Avn Co (Aslt Hel)	0	0	10	8	0	0	0	0
759th Med Det	0	0	3	1	0	0	0	0
205th Avn Co (Aslt Spt Hel)	0	0	8	8	0	0	1	1
213th Avn Co (Aslt Spt Hel)	0	<u>0</u>	9	8_	<u>o</u>	<u>o</u>	1	1
TOTAL 11th Avn Bn (Cbt)	5	٥	51	45	٥	0	4	4

- e. (U) Aircraft Status. See Inclosure 4.
- f. (U) Operational Results. Sec Inclosure 5.
- g. (U) Employment. The 11th Aviation Battalion (Combat) was engaged in daily support of tactical operations during the quarter. Continuous training of new personnel was accomplished concurrently with the conduct of normal combat operations.
 - h. (U) Personnel, Morale, Discipline and Information.
- (1) Personnel Records. An average of 1,150 records were maintained during the period. Processing totals were as follows:

	In Processed	Out Processed
Officor	23	27
Warrant Officer	53	36 ·
Enlisted Man	<u>365</u>	<u>352</u>
Total	441	415

INCL

3

CONFIDENTIAL

AVBACA-AC 13 May 1970 SUBJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

(2) Awards and Decorations. The following awards and decorations were processed this period:

Submitted	Award	Received
0	Silver Star	1
0 .	Legion of Merit	1
67	Distinguished Flying Cross	2
4	Soldior's Medal	6
0	Eronze Star "V"	2
12	Air Medal "V"	17
8	Army Commendation Medal "V"	4
100	Bronze Star	107
1323	Air Medal	1327
410	Army Commendation Medal	426
11	Purple Heart	9

i. (C) Intelligence and Security.

- (1) Throughout this period, weekly intelligence briefings were presented to the Battalian Commander and staff. In addition, periodic intelligence briefings were presented to subordinate units. Intelligence information was gathered from II Field Force, 1st Cavalry Division (Airmobile), 25th Infantry Division, 1st Aviation Brigade, 12th Aviation Group (Combat) and the 23d Artillery Group. Those sources provided intelligence coverage for the entire 11th Aviation Battalian (Combat) area of operations.
- (2) The 12th Aviation Group (Combat) provided current intelligence information to all group aviators, for operation and mission planning. Enemy information resulting from Infrared, "sniffer" and other intelligence reports, was updated at 24 hour intervals. The information received by the 11th Aviation Battalion (Combat) and passed by daily courier to the companies, was posted on the units situation maps for easy pilot reformation. Data was kept posted for 72 hours and removed.

AVBACA_AC 13 May 1970 SUBJECT: CRLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (3) Security. Security measures for the defense of the Battalion aviation assets were altered during this period by the disbanding of the Security Platoon on 22 March 1970. Subsequent to that date, each unit provided a pro rata share of the Battalion's nightly guard commitment at Phu Loi. During this period the Battalion was given the responsibility of maintaining two additional towers and one bunker. Some significant improvements for the defenses of the Battalion aviation assets were made. These include:
 - (a) Repositioning claymore mines and trip flares nightly.
- (b) Strengthening of bunkers through mortar stabilization of deteriorating sandbags.
- (c) Maintaining a responsive command and control group on the bunker line itself with Sergeant of the Guard in charge.
 - j. (C) Plans. Operations and Training.
- (1) Plans. During this reporting period the Battalion Physical Security Plan was revised and updated. The "Scatter" plan for the 173d Aviation Company (Assault Holicoptor), was also revised. The revision of the "Scatter" plan for the 173d Aviation Company was due to the rode-ployment of the 1st Infantry Division from Lai Rho, Base Camp. All other 11th Aviation Battalion (Combat) OPLANS remain in effect.
 - (2) Operations.
- (a) The 11th Aviation Battalion (Combat) supported the following major tactical units: II Field Force, III ARVN Corps, 5th ARVN Division, 1st Cavalry Division (Airmobile), 1st Australian TASK Force, Royal Thai Army Volunteer Force (RTAVF), Long Binh Special Zone (LBSZ), Capitial Filitary District (ChD), Filitary Assistance Command Civil Operations and Revolutionary Development Support (MACCORDS), 5th Special Forces Group, 53d Signal Group, 3d Brigade of the 9th Infantry Division, 199th Light Infantry Brigade, 11th Armorod Cavalry Regiment, and the 62d Engineer Battalion.
- (b) Operation Toan Thang (Complete Victory) Phase IV initiated on 1 November 1969, continued throughout this period. In support of the operation the 11th Aviation Sattalion transported 118,628 passengers and 44,030 tons of cargo while flying 55,041 sorties in 16,118 flying hours (See Inclosure 5). Ession results for this period are found at Inclosure 5. Ammunition expenditures by type and amount are found at Inclosure 6.

AVBACA-AC

13 May 1970

SUBJECT: ORLL For Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (c) Throughout this period airmobile combat assaults (CA), tactical extractions and direct combat support (DCS) missions were conducted daily by the Battalion. During this period the 128th Aviation Company (Assault Helicopter) (minus) provided dedicated support to a special operation conducted by the 5th Special Forces Group in the northeastern portion of the III Corps Tactical Zone. The After Action Report-Lessons Learned is attached at Inclosure 7.
- (d) The 128th and 173d Aviation Companies (Assault Helicopter) of the 11th Aviation Battalion (Combat) provided primary support to the 5th ARVN Division throughout this period. The 213th and 205th Aviation Companies (Assault Support Helicopter) continued to provide general and direct combat support to all major units in III Corps Tactical Zone.
- (c) The 11th Aviation Battalion (Combat) was assigned 39 helibucket fire fighting missions (CH-47 "Chinooks" equipped with two 350 gallon water buckets). Seven of these missions, or eighteen percent, were canceled prior to the aircraft arriving on station. The remaining 32 missions were completed successfully. A total of 213 sorties were flown and resulted in 149,100 gallons of water being dispensed on various types of fires during this period.
- (f) The 11th Aviation Battalion was assigned 91 aircraft recovery missions. Three of these missions involved the recovery of CH-47's by the 213th Aviation Company (Assault Support Helicopter) utilizing the "C" model CH-47. The remaining 88 recoveries involved the recovery of UH-1 aircraft. Two UH-1 were jettisioned due to rigging failure, (See discussion in paragraph 2. c. (2)).

(3) Training.

- (a) During this period 222 personnel (100 percent of these eligible) completed Vietnam in-country training as required by USARV Regulation 350-1. Due to the redeployment of the 1st Infantry Division, replacement training assistance for the 11th Aviation Battalion (Combat) was provided by the 11th Armored Cavalry Regiment, beginning 6 February 1970. During this changeover period the level of in-country training support from the 11th Armored Cavalry Regiment did not meet unit requirements. To compensate for this, 117 of the eligible personnel received in-country training at company level which was conducted in accordance with USARV Regulation 350-1.
- (b) The 11th Aviation Battalion (Combat) continued to assist the ARVN in proper utilization of airmobile assets. Four classes on Airmobile Operations were administered to the 5th ARVN Division during this quarter.

AVBACA-AC 13 May 1970 SUBJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (c) No allocations for the Jungle Environment Survival Training School were received by the 11th Aviation Battalion (Combat). The Battalion currently has two school-trained escape and evasion officers.
- (d) The 11th Aviation Battalion (Combat) Pathfinder Detachment, consisting of 12 personnel, continued its program of parachute training jumps to maintain combat proficiency. A total of 25 jumps were conducted during the quarter.
- (e) The program of hooded flight training was continued throughout the reporting period, with emphasis placed on continued improvement of individual instrument proficiency. In addition to instrument training under the hood, normally conducted during flights to and from operational areas, aviators were required to perform a minimum of two instrument approaches (ADF and/or GCA) monthly.
- (f) Conversational Vietnamese classes for 11th Aviation Battalion aviators and crewmembers commenced on 14 April 1970. The course, consisting of a twenty hour block of instruction, was broken down into two hour periods of instruction scheduled twice weekly for completion during a five week cycle. The present class has ten officers and ten enlisted personnel enrolled. Vietnamese classes are scheduled to continue for an indefinite period.
- (g) Allocations for the Army Aviation Refresher Training School (AARTS) courses continued to decrease. Sixteen allocations were received from 12th Aviation Group (Combat) during the quarter in contrast to twenty-two during the previous quarter. The decrease in allocations is projected to continue. A total of forty-two requests were submitted to 12th Aviation Group (Combat). Allocations were received for the following courses:

COURSE	NO OF ALLOCATIONS
Technical Supply Course	1
CH-47 Maintenance Supervisor Course	2
CH-47 Airframe Repairman Course	5
T-63 Engino Repairman Course	1.
T-53-L-11 Engine Ropairman Course	1
T-53-L-13 Engine Repairman Course	3
CH-47 SAS and Speed Trim Haintonance Course	. 3

AVBACA-AC 13 May 1970 SUBJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

k. (C) Logistics.

- (1) There is a shortage of repair parts at all echelons for the 4,000 pound Forklift, Truck, Ranger 40 Model. There are no repair parts stocked in the Direct Support Unit for this type of equipment. Excessive order/shipping time (six to nine months), is the contributing factor to the high deadline rate of 20 percent for this equipment.
- (2) Units are experiencing difficulty in obtaining A and C level calibration of tools in the Automotive Number 1 and Number 2 Common Tool Sets. The Direct Support Unit refuses to calibrate these tools except for units maintaining tracked vehicles.
- (3) The Battalion continues to have a shortage of 82 M16A1 Rifles as reflected in the ORLL for the period ending 31 January 1970.
- 1. (C) <u>Signal</u>. Continued emphasis was placed on the voice secure program. With the exception of four aircraft which lack ZYS retrofit, (non-available until July), 100 percent installation of KY-28's has been attained. Secure Radio Teletype communication was established with 12th Aviation Group (Combat). The necessity for communications economy and security continues to be stressed throughout the Battalian.

m. (C) Maintenance.

- (1) For all units of the Battalion, the average density was 15 UH-1B/C, each operating an average of 60.5 flying hours per month, 44.6 UH-1D/H aircraft, attaining an average of 91.3 hours each and 31 CH-47A/C aircraft averaging 75.8 hours per month (See Inclosure 8). Seventeen UH-1 aircraft were turned-in, 19 replacements were received. The assault support helicopter companies turned-in five CH-47 helicopters and received four replacements.
- (2) Based on MTOE authorization at the close of the reporting period, the 11th Aviation Battalian (Combat) was short one UH-1B/C and two UH-1D/H aircraft. The 213th Aviation Company (Assault Support Helicopter) operated with only 13 CH-47 aircraft due to turn-ins required to permit full "C" conversions on the 12th Periodic Inspection (PMP). The 205th Aviation Company (Assault Support Helicopter) has 16 CH-47A's assigned.
- (3) A shortage of qualified school trained Technical Inspectors, MOS 67W30, 67U30, and 67N30, for UH-1 and CH-47 aircraft continued to present a problem. With a combined total of 17 authorized and only eight assigned within the Battalion, the work of the Technical Inspector was placed increasingly upon the on-the-job training personnel and maintenance

AVE: CA-AC 13 May 1970 SUBJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

supervisors. With the expected rotational losses and forecast input of Technical Inspectors the problem will become more critical during the next reporting period without continued emphasis on the on-the-job training program.

n. (U) Aviation Safety.

- (1) Two major accidents, four incidents, one forced landing, and fourteen precautionary landings resulted in a cumulative accident rate of 8.9 per 100,000 flying hours. Both major accidents were the result of materiel failure. One accident was caused by engine failure and the other by drive shaft failure. Three incidents were caused by pilot error, the fourth by materiel (engine) failure. Materiel failure was the major cause factor in all forced and precautionary landings.
- (2) Of particular note in the safety program is the fact that the Battalion went through the entire dry monsoon without an accident in which dust was a factor. This accomplishment can be contributed to three factors:
 - (a) The excellent safety programs within units.
 - (b) The professionalism displayed by our aviators.
- (c) The excellent assistance rendered by supported units with regard to dust suppression.

o. (U) Medical.

- (1) The 11th Aviation Battalion (Combat) dispensaries provided primary medical support for 2,571 U.S. personnel and secondary (laboratory and X-ray) support for five other dispensaries supporting an additional 3,000 personnel. There were 2,942 out-patient visits to Battalion medical facilities, including 700 Vietnamose civilians. Time limitations procluded an active off-post MEDCAP program.
- (2) No cases of malaria or other sorious trapical diseases occurred. One case of infections bepatitis and three of bacillary dysentery occurred among Battalion personnel. Eight deaths occurred in the Battalians one as a result of hostile action, four in an aircraft accident, two in a maintenance accident, and one from natural causes. A total of seven injuries occurred as a result of hostile fire.
- (3) Three aircraft accidents were investigated and 203 flight physicals were performed.

AVBACA_AC ... May 1970 SUBJECT: ORLL for Poriod Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

(4) An Optometry Clinic was established in the Battalion Dispensary, operating two days per week on an appointment basis, and staffed by Optometrists from the 24th Evacuation Hospital at Long Binh, Republic of Vietnam.

p. (U) Religious and Personal Sorvices.

- (1) A Group-wide Tri-Faith Roligious Retreat was held 3 20 March at 12th Aviation Group (Combat). It was the first Group-wide religious retreat in Vietnam. The retreat was so successful that a recommendation was made and approved to continue similar retreats every six months. The next retreat is scheduled for September 1970.
- (2) A Sunrise Service was held Easter Sunday, 29 March at 0700 in the 11th Aviation Battalion Chapel area. The Phu Cuong Protestant Church Choir assisted in the service. Utilization of Vietnamese personnel in religious services can and did creato greater interest and response in the units.
- (3) Inclosure 9 reflects a summary of religious activities during this period.

q. (U) Civic Actions.

- (1) The 11th Aviation Battalion (Combat) Civic Action Program was directed toward Community Rolations and Social Welfare projects during this quarter.
- (a) The 128th Aviation Company (Assault Holicopter) and Headquarters and Headquarters Company, 11th Aviation Battalion (Combat) continued to supported the Lai Thieu Deaf Mute School with food staples and clothing.
- (b) The 205th and 213th Aviation Companies (Assault Support Helicopter) continued to support the St. Joseph's Leprosarium near Ben San with diesel fuel and food staples. Self-support at the facility has progressed to the point that the market for the tiles produced there has been surpassed by their ability to manufacture them.
- (c) The 173d Aviation Company (Assault Holicopter) has relinquished control of the Lai Kho Elementary School to the 5th ARVN Division and assumed the support of the Ben Cat Orphanage near Lai kho. As immediate action, in relation to the change over, chicken brooders were constructed and fifty chicks were purchased with funds from the Battalian Donor Deposit Fund and presented to the Orphanage. This project was intended to make the orphanage more self-sufficient.

AVBACA-AC 13 May 1970 SUBJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (2) Progress toward Vietnamese Civic Action awareness was shown as the 5th ARVN Division assumed responsibility of the Lai Khe Elementary School. The Donor Deposit Fund has achieved the desired results of consolidating and controlling the funds available for Civic Action. A new and very active Civic Action Platoon Leader in Binh Duong Province has already made liaison visits to the Battalion and the various unit projects. While no important intelligence data has been gathered as a result of civic action, the lith Aviation Battalion (Combat) is continuing effort in this direction.
- 2. (C) Lessons Learned: Commander's Observations, Evaluations, and Recommendations.
 - a. (U) Personnel. None.
 - b. (C) Intalligonco.
 - (1) (C) Battelion Security Platoon.
- (a) OBSERVATION: On 22 March 1970, the Battalion Security Plateon at Phu Loi was disbanded and the personnel of the plateon were assigned to units of the Battalion. Battalion guard requirements are now filled from the unit guard rosters. This exused the officiency of the perimeter guards to decline semewhat initially, as this duty was relatively unfamiliar to many men.
- (b) EVALUATION: The majority of those individuals detailed for guard are not as preficient in the performance of assigned guard duties as were the individuals in the security plateen. Most of the men work six to eight hours at their assigned duties prior to reporting for guard. This contributes to an overall decline in the efficiency and effectiveness of the security force. Unit strengths have increased but there has been very little increase in unit effectiveness since at least the same number of men gained are detailed for guard duty daily. Furthermore, the time off required for each individual before and after guard duty impairs his job sentimity. Another problem is the additional drain on unit manpower in performing bunkerline maintenance. Presently bunkerline maintenance is performed by a work detail supplied by the units of this command.
- (c) RECOMINDATION: That requested modification of TOE/MTOE submitted 8 June 1969 be reconsidered. Requested modification of personnel allowances is attached at Inclosure 20.
 - (d) COMMAND ACTIONS
- 1 A request for medification of TOE/HTOE has been forwarded through channels.

CONFIDENTIAL

AVBACA-AC 13 May 1270 SUBJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- 2 Comprehensive briefings and inspections are conducted prior to posting guards on the bunkerline.
- 3 The officer of the guard conducts regular inspections of the large erline (once every three hours).
- 4 The sergeant of the guard is positioned at the command and control bunker situated on the bunkerline. Throughout the night he conducts frequent unscheduled inspections to insure that alert posture is maintained.
 - c. (C) Operations.
 - (1) SPH-4 Flight Helmet.
- (a) OBSERVATION: The design and use of the visor on the SEH 4 flight helmet is restrictive.
- (b) EVALUATION: The tinted visor on the SPH-4 flight helmet is difficult to operate and vision is restricted by both night and across hazo conditions. The visor became very difficult to operate in a short period of time due to binding between the visor and its protection shiold, aggreviated by accumulation of dust and dirt in the tracks, The holmet comes with both clear and a tinted visor. However, only one visor can be installed at a time. Since a majority of Battalien mission time is flown during the daylight hours, most pilots installed the tinted visor. The same visor can not be used during night flights and during severe hasing conditions, therefore necessary protection for face and oyes is lost. Recommendation that the clear visor be used and support glasses be worn during the daylight hours has two major disadventages. The first is that when wearing sunglasses, the earphone in the believe is pulled away from the cars and the protection from the extremely high aircraft noise level is lost, The second problem is that wearing of sung glasses under the flight belief is unconfortable and in some cases acceed aviators to develope severe headaches after prelanged uses

(c) RECOMMENDATIONS:

- 1 That the helmot be redesigned to include both a clear and a window visor.
- 2 That all pilots be instructed to perform preventive maintenance on their beliefs to insure that the tracks are along and that the wiser moves freely.

AVBACA-AC 13 May 1970 SUEJECT: ORLL for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- 3 A temporary means of freeing the visor and maintaining free movement can be achieved by applying sdap to the guide tracks positioned in the visor shield.
 - (d) COMMAND ACTIONS:
 - 1 EIR's on the SPH-4 helmet were submitted.
- 2 All aviators in the Battalion have been instructed to inspect their helmets daily to insure that the visor works freely.
 - (2) (C) Aircraft Rocovery Operations.
- (a) OBSERVATION: Failure of forward blade tiodown strap during recovery operations.
- (b) EVALUATION: This unit jottisoned two UH-1 aircraft during recovery operations due to failure of forward reter blade tiedown strap. The failure resulted in oscillations of the aircraft; immediate action to reduce air speed was not effective; escillations increased in severity so rapidly that the UH-1's had to be jettisoned within 15 seconds after the rigging failed. It is evident that adequate supervision and inspection of the rigging on the downed aircraft was not accomplished prior to the recovery. Later evaluation and inspection of rigging equipment used by the recovery unit disclosed that carge tiedown straps used to secure the forward blade were becoming frayed and breaking due to contact with the lower hinge on the pilots and copilots doors.
 - (c) RECOMMENDATIONS:
- 1 That portion of the tiedown strap making contact with the eircraft fuselage be reinforced.
- 2 That recovery air speed for UH-1 aircraft be limited to 60 knots to proclude excessive strain on rigging equipment.
- (d) COMMAND ACTION: Recommondations listed above have been adopted by the Battalian. Ticdown straps were reinforced by inserting a piece of fire hose around that portion of the tiedown strap which makes contact with the aircraft fuselage.
 - d. (U) Organization. None.
 - e. (U) Training. None.
 - f. (C) Logistics.

AVEACA-AC 13 May 1970 SUBJECT: ORLL for Feriod Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- (1) (C) Logistical Support to the INFANT (ENSURE 100) New Famin-ment Training Team.
- (a) OBSERVATION: The team was attached to Headquarters and Headquarters Company, 11th Aviation Battalion (Combat) for logistical support on 5 April 1970. The NEIT was levied to commence training of aviators in the UH-1M helicopter as of 4 May 1970. The team had no internal assets other than the special system and qualified personnel to accomplish the training task.
- (b) EVALUATION: Immediate requirements existed for general support equipment and maintenance support equipment. The 11th Aviation Battalion (Combat) was, and still is, at a disadvantage to support the requirements of the team other than aircraft maintenance.
- (c) RECOMMENDATION: That greater emphasis be placed on the logistical requirements of new concept teams by supporting activities, (i.e., USAICC, Depot) through establishment of sound priorities. Units satellited with such teams should be notified more than 24 hours in advance of the team's arrival so that proper preparations can be made.
- (d) COMMAND ACTION: USAICC and Depot have been advised of the requirements of this unit through official correspondence, lists on visits, and unit requests.
 - g. (U) Communications. None.
 - h. (C) Material.
- (1) (C) Effect on Operational Ready Rates Caused by the Turn-in of UH-1D Aircraft for Out-of-Country Transfer.
- (a) OBSERVATION: The numerous problems encountered in preparing UH-1D aircraft for turn-in for out-of-country transfer necessitated grounding three aircraft for thirty days and caused the Battalian operational roady rate to drop by 6.9 percent.
 - (b) EVALUATIONS:
- 1 The criteria for turn on was not agrablished whom this unit was notified to turn in the Unit alterest.
- 2 The Direct Support Unit would not eccept the direct until they performed a 100 persons technical inspection, and all discrepancies were alough from the DA Form 2001.

AVEACE AC 13 Now 1970
SUBJECT: ORLi for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

- I Initial technical inspections and follow-up inspections were not performed by the same individual. During follow-up inspections, after discrepancies had been cleared from the original DA Form 2404, new DA Form 2404's were prepared and the original form was not used.
- 4 Numerous sheet metal repairs were required to meet turn-in criteria, however the aircraft were flyable.
- 5 Excessive man hours were spent on aircraft for turn-in that could have been devoted to maintenance on the unit's other aircraft.
 - (c) RECOMMENDATIONS:
- 1 Prior to alerting a unit to turn-in aircraft, an exact criteria for turn-in be established with all direct support units in 34th General Support Group.
- 2 That the direct support technical inspectors perform initial inspections and a final inspection using the same DA Form 2404.
- 3 That all sheet motal discrepancies found on aircraft be worked off at the direct support units after the aircraft has been turned-in.
- 4 That operational units be allowed to turn-in aircraft if the man hours to prepare an aircraft for turn-in exceed 750 hours. This would enable the unit to use its manpower more effectively.
- (d) COMMAND ACTION: Numerous limits on visits were conducted with the Direct Support Unit to discuss expediting the turn-in of UH-iD aircraft.
 - (2) (C) Problem Analysis Involving the CH-47C Model Aircraft.
- (a) OBSERVATION: The "C" model availability has been adversely affected and has exceed the EDP rate to be in excess of norms due to the failure of the following components: control panel (FSN 1680-179-1374, part number 114 ES 249-9); bleed band actuator mounting belts (FSN 5306-062-6644) on T-55-L-11 engines; engines changes (FSN 2840-063-0801) due to excessive oil consumption; lack of modification kits for the fuel manifold seals required by HSO 55-2840-234-30/1.
 - (b) EVALUATIONS:
- 1 Failure of three resistors on Card A, samed five control panel units (FSH 1680-179-1374) to short-circuit, in five different occasions aircraft were unable to meet their mission paperting times due to Card A failures.

AVBACA-AC 13 May 1970 SUBJECT: ORLL for Ported Ending 30 April 1970, BCS CSFOR-65 (R2) (U)

- 2 The bleed band actuator mounting bolts (FSN 5306-062-6644) are shearing due to the vibrations posuliar to the "C" model. Those bolts require two to four nan hours to replace, depending on the engine in which the bolts fail.
- 3 Hagines, T-55-L-11 (FSN 2840-063-0001), which are programmed to last 300 hours between overhauls, are removed prior to reaching the 300 hour level due to excessive oil consumption. Two engines have necessitated change at extremely low hour levels, one at 26 hours, and another at 34.
- 4 The lack of modification kits for the fuel manifold seals, required by 1040 55-2840-234-30/1, has caused unnecessary down time. The unit has the capability to perform this modification.

(c) RECOLLENDATIONS:

- 1 That the Card A be modified to eliminate the short circuiting of this panel.
- 2 That botter quality control be established to prevent premature engine removal for excessive oil, and defective bleed band actuator mounting bolts.
- 2 That sufficient modification kits be made available to modify all engines in-country IAW MWO 55-2840-234-30/1.

(d) COMMAND ACTIONS:

- 1 EIR's (H68865, H68866, M39322, M39325 and M39329) have been submitted on all control panel failures and follow-up actions have been taken direct upon request, to AVSCOM.
- 2 EIR's (M39318 and H68844) have been submitted, and VERTOL technical representatives made aware of the failure of the bolt (FSN 5306-062-6644) used on the blood band actuators.
- 2 EIR's (M39327 and M39320) have been submitted and Lycoming technical representatives have been advised of all problems encountered concerning the T-55-L-11 engines.
- 4 The CR-47 project officer has been contacted thru 12th Aviation Group (Combat) and the kits are on Red Ball to CONUS.

AVBACA_AC ORLL for Period Buding 30 April 1970, NOS CSFOR-65 (N2) (U) Subject :

14 (U) Others None.

10 Incl

17 Constal Order Hay, 18th Artetton (Combat)

Commending

2. Organisational Chart

3, Country and Staff Structure

4. Aircraft Status

5. Operational/Mission Results

6. Ameunition Expended 7. After Action Report-Lessons Learned (Project Delta)

8. Aircraft Haintenance Statistical Summary

9. Chapel Statistics

10, Modification Table of Organisation and Equipment Section II - Personnel Allowances

DISTRIBUTION:

5 copies to CO, 12th Aviation Group (Combat)
2 copies to GC, 1st Aviation Brigade
3 copies to CG, USARV

2 copies to GC, CINCUSARPAC

1 copy to CO, 145th Aviation Battalion (Combat)

1 copy to CO, 210th Aviation Battalian (Combat)
1 copy to CO, 222d Aviation Battalian (Combat)
1 copy to CO, 269th Aviation Battalian (Combat)
1 copy to CO, 3d Sqdn, 17th Air Cav

Incls 1, 3 & 9 w/d HQ DA

PRECEDING PAGE BLANK - NOT FILMED

AVBACA-SC (13 May 70) 1st Ind

SUBJECT: Operational Report - Lessons Learned of the 11th Aviation Battalion (Combat) for Period Ending 30 April 1970, RCS-CSFOR-65 (RI) (U)

DA, HEADQUARTERS, 12TH AVIATION GROUP (COMBAT), APO 96266 26 May 1970

TO: Commanding General, II Field Force Vietnam, APO 96266

In compliance with USARV Reg 525-15, the Operational Report - Lessons Learned of the 11th Aviation Battalion (Combat) for the period ending 30 April 1970, is forwarded.

FOR THE COMMANDER:

Cella a Got An. Captain, EN Acting Adjutant

AVFBC-RE (13 Lay 70) 2d Ind SUDJECT: Operational Report - Lessons Learned of the 11th Aviation Battalion (Combat) for Period Ending 30 April 1970, RCS CSFOR-65 (R2) (U)

DA, HQ, II FYOMCEV, APO San Francisco 96266 9 JUN 1970

THRU: Commanding General, 1st Aviation Brigade, ATTN: AVBA-C, APO 96307

Commanding General, US Army Vietnam, ATTN: AVHGC(DST), APO 96375

Commander-In-Chief, US Army Pacific, ATTN: GPOP-DT, APO 96558

- TO: Assistant Chief of Staff for Force Development, Department of the Army, Mashington, D.C. 20310
- 1. (U) This headquarters has reviewed and concurs with the Operational Report Lessons Learned for the quarterly period ending 30 April 1970 from Headquarters, 11th Aviation Battalion (Combat).
- 2. (U) Reference item concerning "Logistical Support to the INTAIT (MISURE 100) New Equipment Training Teams", page 14, paragraph 2f(1), and "Effect on Operational Ready Rates Caused by the Turn-in of UH-1D Aircraft for Out-of-Country Transfer", page 14, paragraph 2h(1): concur. Command action taken by the reporting unit with respect to these items is considered appropriate. The USARV Aviation Officer is being notified of these problems through technical channels in an effort to preclude future occurences.

FOR THE COMMIDER:

CPT, AGC

Asst AG

CF:

CO, 12th Avn Gp (Gbt)

CO, 11th Avn Bn (Cbt)

AVBACC-0 (13 May 70) 3d Ind SUNJECT: Upporational Report-Lessons Learned of the 11th Aviation Battalion (Combat) for Poriod Ending 30 April 1970, RCS CSFCR-65 (P2) (U)

DA, HEAD MARTIES, IST AVIATION DAIGADE, APO 96384 13 JUN 1970

THRU: Commanding General, United States Army Vietnam, ATTM: AVHCC-DST, ATO 96375 Commander-in-Chief, United States Army Pacific, ATTM: GPCP-Df, APO 96558

Assistant Chief of Staff for Forco Dovelopment, Department of the TO: Army, Mashington, D.C. 20310

This headquarters has reviewed the 11th Aviation Battelion (Combat) Operational Report-Lessons Learned, for the period 1 February 1970 - 30 April 1970 and concurs with the basic report and the comments contained in the 2d indorsement with the following exceptions.

- a. Paragraph lk(1), page 3: Farts for the model 40 forklift are in short supply. Faximum use of Red Pall Requisitions will be used. Action by USARV is recormended.
- b. Paragraph 1k(2), page 8: All Erigade units were notified that a calibration team was scheduled to arrive in the Long Binh area in early June. Brigade units will utilize this team to the maximum extent possible.
- c. Paragraph L.(3), page 8: The 12th Aviation Group (Combat) is authorized 4,883 116s, and in lay reported 4,995 on hand. The 12th Aviation Group (Combat) is to effect equitable distribution of available 116 rifles.
- d. Paragraph 2c(2)(b), page 13: The unit discusses the failure of the forward main rotor tiedown strap during recovery operations. Supervision my have been a factor; however, the method of securing the forward blade by passing the strap through the cockpit causes the strap to chafe on the door posts. This is the rajor cause of the tiedown strap failure. The Floating Aircraft Maintenance Facility (FMT) is manufecturing a forward main rotor blade tiedown, which connects to the towing rings in the forward portion of the skid tubes. Eventy-four of these assemblies have been issued to recovery units throughout Vietnam, and 32 more will be available in the near future.
- e. Paragraph 2f(1), page 1/4: Logistical requirements connot be resolved unloss the requirements are known in advance. Closer coordination should have been effected between the 12th Aviation Group (Combat) and the 11th Aviation Pattalion (Combat). Procedures to obtain required surport on a timely basis have been discussed by the Brigado G-4 and the Group S-4.

FOR THE COMMANDER:

WARREN A. PETERSON

CPT, AGC 20 . ASST AG

AVHGC-DST (13 May 70) 4th Ind SUBJECT: Operational Report-Lessons Learned of the 11th Aviation Battalion (Combat), for Quarterly Period Ending 30 April 1970, RCS CSFOR-65 (R2)

Headquarters, United States Army Vietnam, AFO San Francisco 96375

- TO: Commander in Chief, United States Army Pacific, ATTN: GPOP-DT, APO 96558
- 1. This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 30 April 1970 from Headquarters, 11th Aviation Battalion and concurs with comments of indorsing headquarters.

2. Comments follow:

- a. Reference item concerning "SPH-4 Flight Helmet", page 12, paragraph 2c(1). In response to a request by the Safety Division, USARV Aviation, for an evaluation of the Navy-developed SPH-4 double visor kit, USABAAR, on 6 May 1970, stated that the double visor kit is undesirable. Its incorporation would increase the total helmet weight by one-half pound and would move the helmet center of mass forward significantly. An alternative to the redusign of the helmet, yet one which allows the aviator to wear eyaglasses/sunglasses while wearing the SPH-4, is the recently developed, liquid filled ear pad assembly. This pad provides a seal where the eyaglasse frame passes beneath the ear pad. USARV is initiating action to obtain and distribute these pads. Unit has been so advised.
- b. Reference item concerning "Aircraft Recovery Operations", page 13, paragraph 2c(2), and paragraph d, 3d Indorsement: concur with the 3d Indorsement. The new forward main rotor blade tiedown device being manufactured by the FAMF will eliminate this problem. Information concerning this new device is being published in the 34th General Support Group newmletter. No action by DA or USARPAC is recommended.
- c. Reference item concerning "Turn-in of UH-1D Aircraft for Out-of-Country Transfer", page 14, paragraph 2h(1): Geneur. However, units are expected to maintain their aircraft on a continual basis and not to allow the excessive accumulation of deferred maintenance. Aircraft will not be accepted by direct support/general support maintenance units if it is apparent that the owning unit has neglected to perform proper organizational maintenance. A message to this effect was sent to all aviation units on 29 May 1970. No action by DA or USARPAC is recommended.
- d. Reference item concerning "CH-47C Aircraft Problems", page 15, paragraph 2h(2): concur with the recommendation. A new, more reliable card has been developed for the control panel. It is currently a critical item because of the high failure rate of the existing card. A new bleed band actuator mounting

AVHCC-DST (13 May 70) 4th Ind SUBJECT: Operational Report-Lessons Learned of the 11th Aviation Battalion (Combat), for Quarterly Period Ending 30 April 1970, RCS CSFOR-65 (R2)

bolt has been developed and is available; however, existing bolts can be machined to the dimensions of the new bolt. As concerns fuel manifold seals, all CH-47C aircraft have been modified in accordance with MWO 55-2840-234-30/1. Unit has been so advised.

FOR THE COMMANDER:

Clark W. Stevens Je

Assistant Aujutunt General

Cy furn: 1st Avn Bds 11th Avn Bn GPOP-DT (13 May 70) 5th Ind (U)
SUBJECT: Operational Report of HQ, 11th Aviation Battalion (Combat) for
Period Ending 30 April 1970, RCS CSFOR-65 (R2)


HQ, US Army, Pacific, APO San Francisco 96558 17 JUL 70

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, C. D. 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

S.E. OZAKI GPT, AGC Asst AG



11TH AVIATION BATTALION (COMBAT) AIRCRAFT STATUS AS OF 30 APRIL 1970

	ō 	OH-58A			12	• 74					- 4
TEN					מ	1-1				147	
	H H	AUTH ON HAND AUTH	¥GE Y			ON HAND	٩		AITTU	You look	9
				TH-1D	THE 4D THE 40	15			770	CIN TANK	3
,	1				37-00	71-E0	08-10 08-18 UB-16	UH-114		CH-47A	CH 474 GH 476
128th Avn Co (Asit Hel)			31	~		80	1				
1734 Avn Co (Aslt Hel)			31		α.	o					
205th Avn Co (Aslt Spt Hel)	~	C			,	`	.		,		
		•				_			16	92	
Z. Jun .wm to (Acit Spt Hel)	N	0					· •	-	44		-
BN EQ	n	m	-					n	}		7
11th L B (A.)			+	i	-					-	
ייית שאנו דעו (חסב)	~	<u>~</u>	63	2	α	48	70				
					•			•			

į

Anglosare 4

11TH AVIATION BATTALION (COMBAT) OPERATIONAL/MISSION RESULTS FOR THE PERIOD 1 FEBRUARY 1970 THROUGH 30 APRIL 1970

a. Operational Results:

UNIT	SORTIES FLOWN	TROOPS LIFTED	CARGO TONS LIFTED	Hours Flown
128th Avn Co (Aslt Hel)	18,498	42,511	0	5,026
173d Avn Co (Aslt Hel)	12,617	29,886	О	4,708
205th Avn Co (Aslt Spt Hel)	9,586	22,589	22,655	2,982
213th Avn Co (Aslt Spt Hel)	12,213	23,162	21,371	3,007
ви на	2,127	480	4	395
11th Avn Bn (Cbt)	55,041	118,628	44,030	16,118

b. Mission Results:

UNIT	AIRC CBT DAM	raft CBT Loss	ENEMY KIA	STRUC Dam	TURES DEST		Pans Desi	RECOVERIES
128th Avn Co (Aslt Hel)	3	2	5	0	28	0	4	0
173d Avn Co (Aslt Hel)	3 .	0	10	0	6	0	0	0
205th Avn Co (Aslt Spt Hel)	0	0	0	0	0	0	0	11
213th Awn Co (Aslt Spt Hel)	1	0	0	0	0	0	0	80
рн ид	0	0	2	٥	0	0	0	0
11th Avn Bn (Cbt)	7	2	17	0	34	0	4	91

Andlesure 5

11TH AVIATION BATTALION (COLDAT) AMERITION EXPENDED FOR THE PERIOD 1 FEBRUARY 1970 THROUGH 30 APRIL 1970

UNIT	7.62mm	40 _{mm}	2.75 FFAR
128th Avn Co (Aslt Hel)	310,630	0	4,895
173d Avn Co (Aslt Hel)	421,880	o	3, 762
205th Avn Co (Aslt Spt Hel)	3,300	0	o
213th Avn Co (Aslt Spt Hel)	4,150	o	0 ·
BN HQ	11,340	o	0
11th Avn Bn (Cbt)	751,300	0	8,657

AFTER ACTION REPORT-LISSONS LEARNED (PROJECT DELTA)

EXTRACT

- 1. (C) <u>Identity of Operation</u>: The 128th Aviation Company (Assault Helicopter) (minus) was engaged in dedicated support of "Delta Forces", 5th Special Forces Group, from 11 February 1970 to 10 March 1970. The "Delta Forces" were engaged in special recommaissance activities. The operation was conducted in the northeastern portion of III Corps Tactical Zone (See map sheet at Inclosure 1 to Inclosure 7) utilizing Bunard, located at coordinates YT 2987, as the Forward Operations Base (FOB).
- 2. (C) <u>Task Organization</u>: The 128th Aviation Company (minus) consisted of the 2d airlift platoon, the 3d armed platoon and personnel from company operations, communications, maintenance, and avionics sections. The 2d airlift platoon supplied six UH-IH lift aircraft daily and 26 flight crewmembers. The 3d armed platoon supplied four UH-IB gunships and 16 flight crewmembers. Thirteen other personnel from various sections of the unit supported the operation. A total of fifty-five personnel were deployed to FOB Bunard.
- 3. (C) Concept of Operation and Execution: The Delta Forces received the mission to conduct recommaissance operations in AO Tree Top (See map sheet attached at Inclosure 1 to Inclosure 7) to determine location of enemy supply routes in the area. This was accomplished by insorting six man recom teams at various locations throughout the AO to find and fix enemy positions. ARVN Rangers were utilized as a reaction force to support reconnissance teams who inadvortently did engage the enemy.
- 4. (C) Results: The 128th Aviation Company (minus) flew a total of 2,306 sortions in 1,288.2 hours, transported 2,001 troops and conducted 13 medevac missions. The UH-1B gunships fired 103,700 rounds of 7.62mm ammunition, 2,394 10 pound 2.75 rockets and accounted for three VC MIA s, four sampans and countless bunkers hootehes.
- 5. (C) Special Equipment and Techniques: The lift aircraft were equipped with 30 foot troop ladders and McQuire extraction rigs. One aircraft was equipped with a hoist and jungle ponetrator for special recoveries. All landing zones were reconnected by air prior to insertions. Due to torrain configuration and dense foilage, many insertions and extractions were made from a six to ten foot bover. Extractions were normally made at either first or last light utilizing two recovery ships, one command and control aircraft and a light fire team (two UH-1B gunships). On several occasions two light fire teams were required to support the extractions when teams were in contact with the enemy.

28 CONFIDENTIAL

-Inchesure f

AFTER ACTION REPORT-LESSONS LEARNED (PROJECT DELTA)

EETRACT

- 6. (C) Problem Analysis: Problems encountered during this operation were as follows:
- a. The lack of sufficient pensprime in the area directly adjacent to and around the helicopter revetments at Bunard presented a major dust problem. All aircraft maintained at the FOB experienced a marked power loss due to excessive dust intake into the engines. Possibility of going inadvertent IMC in the dust clouds caused by rotorwash was a major safety hazard.
- b. Major problems were experienced in the area of aircraft availability. The supported unit required six flyable UH-1H's and four UH-1B's on a confirmed and dedicated basis. In addition, that portion of the company remaining at base camp was committed for six aircraft daily in support of operations in the III Corps Tactical Zone. This heavy geographically separated commitment over a prolonged period of time reduced the ability of the unit to adhere to sound maintenance management procedures. Within a very short period of time aircraft avialability declined to less than established norms.
- c. POL facilities were not established until the operation had been in progress for two and one half weeks. POL was the responsibility of the supported unit, however, due to their inability to provide adequate POL equipment, this responsibility was assumed by the 11th Aviation Battalion (Combat).

7. (C) Lessons Learned:

- a. That it is imperative that forward bases of operations be prepared to support aviation units prior to their deployment.
- b. When an aviation unit is requested to provide dedicated support on an extended basis in a remote and distant area, the controlling agency should make provisions for maintenance down time and to/from time for replacement of down aircraft.
- c. Maximum training should be conducted in the area of night operations, use of troops ladders, and McQuire rigs prior to commencement of operation. Classes on survival, escape and evasion are imperative.

29

CONFIDENTIAL

11TH AVIATION BATTALION (COMMAT) AIRCRAFT MAINTENANCE STATISTICAL SUMMARY FOR THE PERIOD 1 FEBRUARY 1970 THROUGH 30 APRIL 1970

TYPE AIRCRAFT	FEB	MAR	APR	TOTAL
		Hours Flown		
UH-1B/C UH-1D UH-1H CH-47A CH-47C	1015 1847 2010 1213 1080	863 1771 2404 1382 1303	846 1939 1807 1225 1076	2724 5557 6221 3920 3459
		AVAILABLE (3)		
UH-1B/C UH-1D UH-1H CH-47A CH-47C	70.2 74.3 80.7 85.2 82.4	63.2 70.1 83.5 79.1 79.1	59.4 44.4 75.1 80.9 74.4	64.3 64.0 79.9 82.0 79.0
		NORM (%)		
UH-1B/C UJ-1D UH-1H CH-474 CH-47C	18.0 24.5 18.6 12.3 17.1	27.8 30.8 16.5 16.9 20.2	33.9 50.4 21.1 16.8 23.6	26.6 34.3 18.7 15.1 20.2
		Nors (\$)		
UE-1B/C UH-1D UH-1H CH-474 CH-47C	11.8 2.6 0.7 2.5 0.0	8.9 0.0 0.0 4.0 0.7	6.7 5.2 3.8 2.3 2.0	9.1 1.7 1.4 2.9 0.8

MOD	IFIC	ATION TABLE OF ORGANIZA SECTION II - P	TION AN	D EQUI	PMEN WANC	T C	MD US	OB 1- BARPAC PAKKA	256G 1/6	8	
IND	EX					STREN	GTH LE	/RIS	RE	MARKS	
	ь	DESCRIPTION	GR d	MOS :	BR	1	h	1	1	2 k	3
		SECG1256G6081									
09		SECURITY PLATOON HO									
	01	PLATOON LEADER	LI	1542	IN	1					A1
	02	PLATOON SERGEANT	E 7	11B40	IN	1					A 1
	03	LT TRUCK DRIVER	E4	64A10		2					A2
ī	04	AMMO SPECIALIST	B 5	5 5 B30		1					A1
10		SECURITY SQUADS									
	01	squad leader	E 6	11B40	IN	3					A 3
	02	SECURITY GUARD	13/4	11B20		12					A12
	03	SECURITY GUARD	B 3	11B20		30					A 30
		TOTAL				50			Ì		A50
		•									
								i.			
					ŀ						
-	1	A C	- a		+-	-	-	 	+-	+-	 _

UNCLASSIFIED
Security Classification DOCUMENT CONTROL DATA - R & D (Security classification of title, body of abstract and indexing remotation must be entered when the overall report is classified, 1. ORIGINATING ACTIVITY (Corporate suther) 20. REPORT SECURITY CLASSIFICATION CONFIDENTIAL HQ, OACSFOR, DA, Washington, D.C. 20310 S. REPORT TITLE Operational Report - Lessons Learned, HQ, 11th Aviation Battalion 4. DESCRIPTIVE HOTES (Type of report and inclusive dates) Experiences of unit engaged in counterinsurgency operations, s. AUTHOR(8) (First mame, middle initial, last name) CO, 11th Aviation Battalion . REPORT DATE A. TOTAL HO. OF PAGES 13 May 1970 M. ORIGINATOR'S REPORT NUMBER(S) b. PROJECT NO. N/A 702059 66. OTHER REPORT NO(5) (Any other numbers that may be essigned this report) 10. DISTRIBUTION STATEMENT 2. SPONSORING MILITARY ACTIVITY II. SUPPLEMENTARY NOTES OACSFOR, DA, Washington, D.C. 20310 N/A 13. ABSTRACT

32